## MOUNT PLEASANT CONSERVATION AREA RECORD OF ALTERATIONS, APPROVALS AND REFUSALS OF PERMISSION LISTED BY INDIVIDUAL PROPERTY.

## Film frame & roll No

| & roll No           |                               |    |   |
|---------------------|-------------------------------|----|---|
| Mill Yard           | 18/19 <sup>th</sup> C         | II | Rear and front burglar alarm( items in green indicate         |
| House               |                               |    | unauthorised changes)   |
| 23 & 242            |                               |    | 0 /   |
| Mill House          | 18/19 <sup>th</sup> C         | II |   |
| 252                 |                               |    |   |
| 1 & 23              |                               |    |   |
| Mill Cottage        |                               |    |   |
| 222                 |                               |    |   |
| Lord Raglan         | 19 <sup>th</sup> C            | II | Unauthorised Pvcu windows originally to ground floor now      |
| P.H.                | 15 0                          | 11 | throughout.   |
|                     |                               |    | in oughout.   |
| 6 & 71              | Late 19 <sup>th</sup>         | II | 30204/94. Ext. to existing outbuildings & relocation of       |
| 142                 | Century                       | 11 | gateway.  |
| 172                 | Century                       |    | 31794/96. LBC – Conversion of loft.                           |
|                     |                               |    |   |
| 2                   | Late 19 <sup>th</sup>         | II | White burglar alarm to gable. BR/4/74/171. Kitchen extension. |
|                     |                               | 11 | DN/4//4/1/1. KIUHEH EXICHSIOH.                                |
| 152                 | Century Late 19 <sup>th</sup> | II | 21124/99 I DC to made as a sind asset                         |
| 3                   |                               | II | 21134/88. LBC to replace windows.                             |
| 162                 | Century                       | TT | Pvcu windows in place.  |
| 4                   | Late 19 <sup>th</sup>         | II | 12878/81. LBC to replace windows.                             |
| 172                 | Century                       |    | 25198/90. LBC to replace windows.                             |
|                     | th                            |    | 36596/00. LBC Rear s/s porch and alts to rear outbuilding.    |
| 5                   | Late 19 <sup>th</sup>         | II | 12193/81. LBC aluminium frames to wooden <b>REFUSED</b>       |
| 182                 | Century                       |    | 12571/81. As above. Approved after appeal.                    |
|                     |                               |    | 33727/97. LBC S/S we and porch to rear                        |
| 6                   | Late 19 <sup>th</sup>         | II | 12656/81. Replacement windows.                                |
| <i>19, 20 &amp;</i> | Century                       |    |   |
| 212                 |                               |    |   |
|                     |                               |    |   |
|                     |                               |    |   |
| 8                   | 19 <sup>th</sup> C            | II | Satellite dish on back wall.                                  |
| 121                 |                               |    |   |
| 9                   | 19 <sup>th</sup> C            | II | New dish on chimney.  |
| 111                 |                               |    | 37390/01 LBC loft conversion & replacement windows            |
| 10                  | 19 <sup>th</sup> C            | II | 03555/76. LBC new windows.                                    |
| 101                 |                               |    | New dish on chimney. New canopy to front door.                |
| 11                  | Early                         | II | 9.10.03. New UPVC fascia being installed. Full renovation     |
| 91                  | 19 <sup>th</sup> C            |    | over last 5 years without any applications for LBC.           |
| 12                  | Early                         | II | 11906/81. LBC. Aluminium windows with H/W surrounds.          |
| 81                  | 19 <sup>th</sup> C            |    | REFUSED   |
| J1                  |                               |    | Burglar alarm box fitted front and rear.                      |
| 13                  | Early                         | II | Alarm box fitted to front. Various works for alteration and   |
| 141                 | 19 <sup>th</sup> C            | ** | upgrading, both internal and external. Sept 03 utility box    |
| 171                 | 17 0                          |    | and disturbance of sett roadway.                              |
|                     | I                             | I  | and distarbance of sen roddwdy.                               |

| House No | Year | Grade | Applications |
|----------|------|-------|--------------|
|----------|------|-------|--------------|

| 14       | 151      | Early<br>19 <sup>th</sup> C                       | II | 11907/81. LBC. Aluminium windows with H/W surrounds.  REFUSED   |
|----------|----------|---|----|---|
| 15<br>15 | cont 161 | Early<br>19 <sup>th</sup> C                       | II | 34471/98. LBC. Child security gates to rear. Now removed  |
| 16       | 171      | Early<br>19 <sup>th</sup> C                       | II |   |
| 17       | 181      | Early<br>19 <sup>th</sup> C                       | II | 24390/90. Satellite Dish  REFUSED  Alarm box at rear.   |
| 18       | 191      | Early<br>19 <sup>th</sup> C                       | II | 17999/86. LBC. Replacement windows.  Pvcu windows in place front and rear.  Gas flue rear roof  |
| 19       | 201      | Early<br>19 <sup>th</sup> C                       | II | Alarm box fitted.   |
| 20       | 211      | Early<br>19 <sup>th</sup> C                       | II | 27971/92. LBC. Window to rear.<br>29726/94. Con Area consent, demolition of outhouse.<br>38396/01 LBC new hardwood front door.  |
| 21       | 221      | Early<br>19 <sup>th</sup> C                       | II | Alarm Box fitted to front. Gas flue rear roof.  |
| 22       | 231      | Early<br>19 <sup>th</sup> C                       | II |   |
| 23       | 241      | Early<br>19 <sup>th</sup> C                       | II | Gas flue front wall.  |
| 24       | 12       | Early<br>19 <sup>th</sup> C                       | II | 16260/84. LBC. Additional window.   |
| 25       | 22       | 19 <sup>th</sup> C<br>Early<br>19 <sup>th</sup> C | II | 21012/88. LBC. Replace doors and windows.  Pvcu windows in place front and rear. Chimney stack removed. Satellite dish in rear garden.  |
| 26       | 32       | Early<br>19 <sup>th</sup> C                       | II | 28081/93. Con to rear. <b>REFUSED</b> 30370/94. LBC. Canopy over back door. Alarm box fitted to front.  |
| 27       | 42       | Early<br>19 <sup>th</sup> C                       | II | 15762/84. LBC. Replacement windows. <i>New boiler flue to roof Nov 2002.</i>  |
| 28       | 5 & 62   | Early<br>19 <sup>th</sup> C                       | II | 12357/81. LBC window to grd floor gable end Alarm box fitted to front Satellite dish erected to stack, reported 22/9/03   |
| 29       | 72       |   |    | Garages.  |
| 30       | 82       | Early<br>19 <sup>th</sup> C                       | II | 10746/80. Con to rear. 13746/82. LBC. Kit Ext to rear 21962/88. Alts of window frames on all elevations. 36843/00. LBC demolition of S/S garage at side and erection of new 2 storey ext to side. Compliance with approved scheme questioned. Dish to stack. White UPVC at rear. Concrete and waney lap |

|              |                             |    | fences to rear and side. Issues of boundaries and ownership. |
|--------------|-----------------------------|----|--|
| A d: #20     |                             |    |  |
| Adj #30      | Darler                      | П  | 13755/82. Erection of garage                                 |
| 92           | Early<br>19 <sup>th</sup> C | II |  |
| 32           | Early                       | II | 28950/93. LBC. Conservatory to rear.                         |
| 102          | 19 <sup>th</sup> C          |    | REFUSED  |
|              |                             |    | White upvc windows to rear and brown to front.               |
| 33           | Early                       | II | 13331/82. LBC Alts and renovations (grant)                   |
| 112          | 19 <sup>th</sup> C          |    | Pvcu windows in place at rear including french windows.      |
|              |                             |    | Pvcu in front now replaced with timber.                      |
|              |                             |    | 36746/00 Replacement windows & Doors <b>REFUSED</b>          |
| 34           | Early                       | II | 00073/74. Alts to garage.                                    |
| 12 & 132     | 19 <sup>th</sup> C          |    | 13623/82. Kitchen ext and detached garage.                   |
|              |                             |    | 16913/85. Alts to external appearance of garage.             |
|              |                             |    | 17357/85. LBC Window to attic store.                         |
|              |                             |    | 36060/99. Demolition of extg structure, continuation of extg |
|              |                             |    | perimeter wall and replace extg porch with small stone based |
| 34 continued |                             |    | conservatory.  |
| 12 & 132     |                             |    | 36061/99. Continuation and replace porch with small stone    |
| 12 & 152     |                             |    | based conservatory.  |
|              |                             |    | 40572/03. LBC. New frames to 2 windows. Approved and         |
|              |                             |    | installed.   |
| 35           | 19 <sup>th</sup> C          | II | White alarm box in place. Satellite dish on chimney 12/02.   |
| 33           |                             | "  | while didn't box in piace. Saletite dish on chimney 12/02.   |
| 36           | 19 <sup>th</sup> C          | II | Loft conversion and skylight.                                |
| 43           |                             |    |  |
| 31           | 19 <sup>th</sup> C          | II | 25018/90. LBC. Demolition of extg rear porch and erection    |
| 53           |                             |    | of ext to rear.  |
|              |                             |    | 30186/94. LBC. Installation of skylight to roof.             |
| 38           | 19 <sup>th</sup> C          | II | Satellite dish to chimney.                                   |
| 63           |                             |    |  |
| 39           | 19 <sup>th</sup> C          | II | 32588/96. LBC porch to rear.                                 |
| 73           |                             |    | 32589/96. Con area consent demolition of rear porch.         |
| 40           | 19 <sup>th</sup> C          | II | 18667/86. Partial demolition and improvements.               |
| 8 & 93       |                             |    | 19534/87. Canopy over rear door.                             |
|              |                             |    | 32610/96. LBC rear porch. Built 1997.                        |
| 41           | 19 <sup>th</sup> C          | II | Satellite dish to front garden.                              |
| 103          |                             |    |  |
| 42           | 19 <sup>th</sup> C          | II | New windows January 2003. Satellite dish to chimney front.   |
| 113          |                             |    |  |
| 43           | 19 <sup>th</sup> C          | II | 30132/94. LBC. Roof light to rear. New door to rear.         |
| 123          |                             |    | Satellite dish to front garden.                              |
| 44           | 19 <sup>th</sup> C          | II | 45 and 44 knocked through in to one dwelling. Soil pipe      |
| 133          |                             | 1  | appeared early 2003. Building regs and LBC for knocking      |
| 155          |                             |    | through? Wide french windows and lowered cill to other       |
|              |                             |    | window at the rear.  |
|              |                             | L  | mander at the real.  |

| <b>House No</b> | Year | Grade | <b>Applications</b> |
|-----------------|------|-------|---------------------|
|-----------------|------|-------|---------------------|

| 45            | 19 <sup>th</sup> C | II  | As above + new unauthorised windows to front elevation   |
|---------------|--------------------|-----|--|
| 45<br>143     | 19 C               | 111 | inserted separately 2003. Skylight to roof.  |
| 46            | 19 <sup>th</sup> C | II  | 30198/94. LBC porch to rear.   |
| 15 3          |                    | 11  | 30170/74. LDC poten to teat.   |
| 153<br>47     | 19 <sup>th</sup> C | II  | Satellite dish to rear of chimney.   |
| 16 2          |                    | 11  | Saletitle dish to rear of chimney.   |
| 163<br>R/O 47 | 19 <sup>th</sup> C | II  | 02429/75. Loose box stable for 2 horses.   |
| 10/04/        | 19 C               | 11  | 04137/76. Renewal of above.  |
|               |                    |     | 06433/78. Isolation box/stable   |
|               |                    |     | 09791/80. Loose box renewal.   |
|               |                    |     |  |
|               |                    |     | 12472/81. Isolation box renewal  |
|               |                    |     | 14366/83. Loose box retention.   |
|               |                    |     | 17207/85. Stable block retention.  |
| 48            | 19 <sup>th</sup> C | II  | Satellite dish to front garden.  |
| 173           |                    |     |  |
| 49            | 19 <sup>th</sup> C | II  | Satellite dish to front of chimney. Skylight in roof.  |
| 183           |                    |     |  |
| 50            |                    |     | Internal alterations and possible removal of walls   |
| 193           |                    |     | Francisco Since Si |
| 51            |                    |     | Burglar alarm. Possible removal of internal fire doors.  |
| 31            |                    |     | Burgiar diarm. I ossible removal of internal fire doors.   |
|               |                    |     |  |
| 52            |                    |     |  |
|               |                    |     |  |
| 53            |                    |     | Alarm Boxes front and rear   |
|               |                    |     |  |
| 54            |                    |     | Gas flue at rear.  |
|               |                    |     |  |
| 55            |                    |     | Alama havas front and no su  |
| 33            |                    |     | Alarm boxes front and rear   |
|               |                    |     |  |
| 56            |                    |     | <i>Upvc front door. Flue front roof – and extended 08/03.Pvcu</i>  |
|               |                    |     | windows and doors to rear.   |
| 57            |                    |     | Gas flue to roof.  |
|               |                    |     |  |
| 58            |                    | 1   |  |
|               |                    |     |  |
| 50            |                    |     | D 11 11  |
| 59            |                    |     | Pvcu windows and doors at rear.  |
|               |                    |     |  |
| 60            |                    |     |  |
|               |                    |     |  |
| 61            |                    |     |  |
|               |                    |     |  |
| (2)           |                    | 1   |  |
| 62            |                    |     |  |
|               |                    |     |  |

| House No | Year | Grade | Applications   |
|----------|------|-------|--|
| 63       |      |       |  |
| 64       |      |       |  |
| 65       |      |       |  |
| 66       |      |       |  |
| 67       |      |       |  |
| 68       |      |       |  |
| 69       |      |       | Burglar boxes front and rear   |
| 70       |      |       | Pvcu french windows to rear.   |
| 71       |      |       |  |
| 72       |      |       | Burglar alarm to rear and front.   |
| 73       |      |       | Replacement of bathroom window.  |
| 74       |      |       | Upvc windows to ground floor front and rear. TV aerial to chimney.                 |
| 75       |      |       | Upvc all around front and rear, burglar alarm boxes front and rear                 |
| 76       |      |       |  |
| 77       |      |       | Upvc windows to front and rear, doors to rear.                                     |
| 78       |      |       |  |
| 79       |      |       | 35414/99 Erection of decking to rear.  .Burglar alarm box to rear.                 |
| 80       |      |       | 35414/99. Erection of decking to rear.   |
| 81       |      |       |  |
| 82       |      |       | Upvc windows to east elevation.  |
| 83       |      |       | Upvc windows to both elevations. Burglar alarm box to rear Satellite dish to gable |

| Year | Grade | Applications  |
|------|-------|---|
|      |       | Upvc to east elevation. Burglar alarm box and satellite dish to rear. |
|      |       | Upvc to east elevation. Burglar alarm box and satellite dish to rear. |
|      |       |   |
|      |       | New fencing.  |
|      |       |   |
|      | Year  | Year Grade  |