## MOUNT PLEASANT CONSERVATION AREA RECORD OF ALTERATIONS, APPROVALS AND REFUSALS OF PERMISSION LISTED BY INDIVIDUAL PROPERTY.

## Film frame & roll No

& roll No			
Mill Yard	18/19 <sup>th</sup> C	II	Rear and front burglar alarm( items in green indicate
House			unauthorised changes)
23 & 242			0 /
Mill House	18/19 <sup>th</sup> C	II	
252			
1 & 23			
Mill Cottage			
222			
Lord Raglan	19 <sup>th</sup> C	II	Unauthorised Pvcu windows originally to ground floor now
P.H.	15 0	11	throughout.
			in oughout.
6 & 71	Late 19 <sup>th</sup>	II	30204/94. Ext. to existing outbuildings & relocation of
142	Century	11	gateway.
172	Century		31794/96. LBC – Conversion of loft.
2	Late 19 <sup>th</sup>	II	White burglar alarm to gable. BR/4/74/171. Kitchen extension.
		11	DN/4//4/1/1. KIUHEH EXICHSIOH.
152	Century Late 19 <sup>th</sup>	II	21124/99 I DC to made as a sind asset
3		II	21134/88. LBC to replace windows.
162	Century	TT	Pvcu windows in place.
4	Late 19 <sup>th</sup>	II	12878/81. LBC to replace windows.
172	Century		25198/90. LBC to replace windows.
	th		36596/00. LBC Rear s/s porch and alts to rear outbuilding.
5	Late 19 <sup>th</sup>	II	12193/81. LBC aluminium frames to wooden <b>REFUSED</b>
182	Century		12571/81. As above. Approved after appeal.
			33727/97. LBC S/S we and porch to rear
6	Late 19 <sup>th</sup>	II	12656/81. Replacement windows.
<i>19, 20 &amp;</i>	Century		
212			
8	19 <sup>th</sup> C	II	Satellite dish on back wall.
121			
9	19 <sup>th</sup> C	II	New dish on chimney.
111			37390/01 LBC loft conversion & replacement windows
10	19 <sup>th</sup> C	II	03555/76. LBC new windows.
101			New dish on chimney. New canopy to front door.
11	Early	II	9.10.03. New UPVC fascia being installed. Full renovation
91	19 <sup>th</sup> C		over last 5 years without any applications for LBC.
12	Early	II	11906/81. LBC. Aluminium windows with H/W surrounds.
81	19 <sup>th</sup> C		REFUSED
J1			Burglar alarm box fitted front and rear.
13	Early	II	Alarm box fitted to front. Various works for alteration and
141	19 <sup>th</sup> C	**	upgrading, both internal and external. Sept 03 utility box
171	17 0		and disturbance of sett roadway.
	I	I	and distarbance of sen roddwdy.

House No	Year	Grade	Applications
----------	------	-------	--------------

14	151	Early 19 <sup>th</sup> C	II	11907/81. LBC. Aluminium windows with H/W surrounds.  REFUSED
15 15	cont 161	Early 19 <sup>th</sup> C	II	34471/98. LBC. Child security gates to rear. Now removed
16	171	Early 19 <sup>th</sup> C	II	
17	181	Early 19 <sup>th</sup> C	II	24390/90. Satellite Dish  REFUSED  Alarm box at rear.
18	191	Early 19 <sup>th</sup> C	II	17999/86. LBC. Replacement windows.  Pvcu windows in place front and rear.  Gas flue rear roof
19	201	Early 19 <sup>th</sup> C	II	Alarm box fitted.
20	211	Early 19 <sup>th</sup> C	II	27971/92. LBC. Window to rear. 29726/94. Con Area consent, demolition of outhouse. 38396/01 LBC new hardwood front door.
21	221	Early 19 <sup>th</sup> C	II	Alarm Box fitted to front. Gas flue rear roof.
22	231	Early 19 <sup>th</sup> C	II	
23	241	Early 19 <sup>th</sup> C	II	Gas flue front wall.
24	12	Early 19 <sup>th</sup> C	II	16260/84. LBC. Additional window.
25	22	19 <sup>th</sup> C Early 19 <sup>th</sup> C	II	21012/88. LBC. Replace doors and windows.  Pvcu windows in place front and rear. Chimney stack removed. Satellite dish in rear garden.
26	32	Early 19 <sup>th</sup> C	II	28081/93. Con to rear. <b>REFUSED</b> 30370/94. LBC. Canopy over back door. Alarm box fitted to front.
27	42	Early 19 <sup>th</sup> C	II	15762/84. LBC. Replacement windows. <i>New boiler flue to roof Nov 2002.</i>
28	5 & 62	Early 19 <sup>th</sup> C	II	12357/81. LBC window to grd floor gable end Alarm box fitted to front Satellite dish erected to stack, reported 22/9/03
29	72			Garages.
30	82	Early 19 <sup>th</sup> C	II	10746/80. Con to rear. 13746/82. LBC. Kit Ext to rear 21962/88. Alts of window frames on all elevations. 36843/00. LBC demolition of S/S garage at side and erection of new 2 storey ext to side. Compliance with approved scheme questioned. Dish to stack. White UPVC at rear. Concrete and waney lap

			fences to rear and side. Issues of boundaries and ownership.
A d: #20			
Adj #30	Dag1-	II	13755/82. Erection of garage
92	Early 19 <sup>th</sup> C	II	
32	Early	II	28950/93. LBC. Conservatory to rear.
102	19 <sup>th</sup> C		REFUSED
			White upvc windows to rear and brown to front.
33	Early	II	13331/82. LBC Alts and renovations (grant)
112	19 <sup>th</sup> C		Pvcu windows in place at rear including french windows.
			Pvcu in front now replaced with timber.
			36746/00 Replacement windows & Doors <b>REFUSED</b>
34	Early	II	00073/74. Alts to garage.
12 & 132	19 <sup>th</sup> C		13623/82. Kitchen ext and detached garage.
			16913/85. Alts to external appearance of garage.
			17357/85. LBC Window to attic store.
			36060/99. Demolition of extg structure, continuation of extg
			perimeter wall and replace extg porch with small stone based
34 continued			conservatory.
12 & 132			36061/99. Continuation and replace porch with small stone
12 60 10 11112			based conservatory.
			40572/03. LBC. New frames to 2 windows. Approved and
			installed.
35	19 <sup>th</sup> C	II	White alarm box in place. Satellite dish on chimney 12/02.
33		11	white diarm box in place. Saletile dish on chimney 12/02.
36	19 <sup>th</sup> C	II	Loft conversion and skylight.
43			
31	19 <sup>th</sup> C	II	25018/90. LBC. Demolition of extg rear porch and erection
53			of ext to rear.
			30186/94. LBC. Installation of skylight to roof.
38	19 <sup>th</sup> C	II	Satellite dish to chimney.
63			
39	19 <sup>th</sup> C	II	32588/96. LBC porch to rear.
73			32589/96. Con area consent demolition of rear porch.
40	19 <sup>th</sup> C	II	18667/86. Partial demolition and improvements.
8 & 93			19534/87. Canopy over rear door.
			32610/96. LBC rear porch. Built 1997.
41	19 <sup>th</sup> C	II	Satellite dish to front garden.
103			
42	19 <sup>th</sup> C	II	New windows January 2003. Satellite dish to chimney front.
113			
43	19 <sup>th</sup> C	II	30132/94. LBC. Roof light to rear. New door to rear.
123			Satellite dish to front garden.
44	19 <sup>th</sup> C	II	45 and 44 knocked through in to one dwelling. Soil pipe
133			appeared early 2003. Building regs and LBC for knocking
155			through? Wide french windows and lowered cill to other
			window at the rear.
			minuon at the real.

<b>House No</b>	Year	Grade	<b>Applications</b>
-----------------	------	-------	---------------------

45	19 <sup>th</sup> C	II	As above + new unauthorised windows to front elevation
45 143	19 C	111	inserted separately 2003. Skylight to roof.
46	19 <sup>th</sup> C	II	30198/94. LBC porch to rear.
15 3		11	30170/74. LDC poten to teat.
153 47	19 <sup>th</sup> C	II	Satellite dish to rear of chimney.
16 2		11	Saletitle dish to rear of chimney.
163 R/O 47	19 <sup>th</sup> C	II	02429/75. Loose box stable for 2 horses.
10/04/	19 C	11	04137/76. Renewal of above.
			06433/78. Isolation box/stable
			09791/80. Loose box renewal.
			12472/81. Isolation box renewal
			14366/83. Loose box retention.
			17207/85. Stable block retention.
48	19 <sup>th</sup> C	II	Satellite dish to front garden.
173			
49	19 <sup>th</sup> C	II	Satellite dish to front of chimney. Skylight in roof.
183			
50			Internal alterations and possible removal of walls
193			Francisco Since Si
51			Burglar alarm. Possible removal of internal fire doors.
31			Burgiar diarm. I ossible removal of internal fire doors.
52			
53			Alarm Boxes front and rear
54			Gas flue at rear.
55			Alama havas front and no su
33			Alarm boxes front and rear
56			<i>Upvc front door. Flue front roof – and extended 08/03.Pvcu</i>
			windows and doors to rear.
57			Gas flue to roof.
58		1	
50			D 11 11
59			Pvcu windows and doors at rear.
60			
61			
(2)		1	
62			

House No	Year	Grade	Applications
63			
64			
65			
66			
67			
68			
69			Burglar boxes front and rear
70			Pvcu french windows to rear.
71			
72			Burglar alarm to rear and front.
73			Replacement of bathroom window.
74			Upvc windows to ground floor front and rear. TV aerial to chimney.
75			Upvc all around front and rear, burglar alarm boxes front and rear
76			
77			Upvc windows to front and rear, doors to rear.
78			
79			35414/99 Erection of decking to rear.  .Burglar alarm box to rear.
80			35414/99. Erection of decking to rear.
81			
82			Upvc windows to east elevation.
83			Upvc windows to both elevations. Burglar alarm box to rear Satellite dish to gable

Year	Grade	Applications
		Upvc to east elevation. Burglar alarm box and satellite dish to rear.
		Upvc to east elevation. Burglar alarm box and satellite dish to rear.
		New fencing.
	Year	Year Grade